


MONTAGEANLEITUNG

Frühbeetaufsatz

WMHPS-GH2510A







**BEI FRAGEN, KONTAKTIEREN SIE
UNSEREN KUNDENSERVICE:**




















50NRTH GmbH
Straßburgstraße 14-16
D-54516 Wittlich



service@50NRTH.com
+49 (0) 6571 95117-0





40Min

Ax1 	Bx1 	Cx1 	Dx1 	Ex1 
Fx1 	Gx2 	Hx2 	Ix1 	Jx13  M4x40
Kx6  M4x10	Lx8  M4x14	Mx1 	Nx1  2.5# T20	Ox4  M4x14
Px4  φ6.2-φ9-2	Qx2 			


STEP1






STEP2



Jx4




STEP3




Jx5




STEP4-1



STEP4-2




STEP5




Lx4



STEP6





STEP7





STEP8



STEP8



STEP9



Kx4